

Asbestos Containing Materials by Property – updated 11/18/2016

Building	Identified or Presumed Asbestos Containing Building Material
Baker Commons	Sink undercoating
Broadway	Presumed in roofing material
Evelyn	Presumed in roofing material
Garden	None
Green Baxter	Drywall Systems, heat shield, floor tile and presumed roofing materials
Hikone	Drywall Systems, heat shield, floor tile/underlayment and presumed roofing materials
Hillside Manor	Presumed in roofing material – replaced in 2015
Lower Platt 3451 – 3457 Platt	Drywall systems, unit 3451 flooring, presumed roofing
Mallets Creek	Presumed in roofing material – replaced in 2015
Maple Meadows	Drywall Systems, heat shield, floor tile and presumed roofing materials
Miller Manor	Drywall Systems tower portion of building only, floor tile/mastic, sink undercoating, exterior cement caulk, ceiling tile (removed) and presumed roofing materials
New Platt	3401 white floor tile in utility room, 3405 cleared
Oakwood	Drywall Systems in 3565 and 3575 only, roof replaced in 2014
Seventh	Presumed in roofing material – replaced in 2016
Upper Platt 3681 -3689 Platt	Presumed in roofing material – replaced removed in 2016, presumed cloth duct isolation joints in basements
West Arbor on North Maple	New Construction 2016, 3-bdr duplexes cleared
W. Washington	Presumed in roofing material – replaced in 2015
White/State/Henry	Building 701 rear exterior window caulk, rear speak panel board exterior calk all buildings, presumed roofing material
Industrial	Floor tile, exterior window caulk and glaze, vermiculite insulation, presumed in electrical wire insulation

TEST RESULTS are posted at www.a2gov.org/housingcommission