

Asbestos Containing Materials by Property – updated 12/5/2019

Building	Identified or Presumed Asbestos Containing Building Material
Baker Commons	Sink undercoating
Broadway	Presumed in roofing material
Garden	None
Green Baxter	Drywall Systems, heat shield, floor tile and presumed roofing materials. None in building 1725-1735 newly constructed in 2015
Hikone	Drywall Systems, heat shield, floor tile/underlayment and presumed roofing materials
Hillside Manor	Presumed in old roofing material – Roof replaced in 2015
Lower Platt 3421 – 3429 Platt	None – new construction 2019
Mallets Creek	Presumed in old roofing material – Roof replaced in 2015
Maple Meadows	Drywall Systems, heat shield, floor tile and presumed roofing materials
Miller Manor	Drywall Systems tower portion of building only, floor tile/mastic (removed in 2013), sink undercoating, exterior cement caulk, ceiling tile (removed in 2015) and presumed roofing materials
Oakwood	Drywall Systems in 3565 and 3575 only, roof replaced in 2014
Seventh	Presumed in old roofing material – roof replaced in 2016
Upper Platt 3681 -3689 Platt	Presumed in old roofing material – roof replaced in 2016, presumed cloth duct isolation joints in basements
West Arbor on North Maple	New Construction 2016, 3-bdr duplexes cleared
W. Washington	Presumed in roofing old material – roof replaced in 2015
White/State/Henry	None – new construction 2019
Industrial	Floor tile, exterior window caulk and glaze, vermiculite insulation, presumed in electrical wire insulation

TEST RESULTS are posted at www.a2gov.org/housingcommission