

Limited Asbestos-Containing Materials Inspection
1504-1508 Broadway Street
Ann Arbor, Michigan

Ann Arbor Housing Commission

November 11, 2013

ASTI ENVIRONMENTAL



Limited Asbestos-Containing Materials Inspection
1504-1508 Broadway Street
Ann Arbor, Michigan

November 11, 2013

Prepared For:


Ann Arbor Housing Commission
404 North Ashley
Ann Arbor, Michigan, 48103

Prepared By:

ASTI Environmental
10448 Citation Drive, Suite 100
Brighton, Michigan 48116
1-800-395-ASTI

ASTI Project 8563

Report Prepared by:



Kevin Ushery
Asbestos Inspector No. A34315

Report Reviewed by:



Robert C. Anderson P.G.
Director - Site Redevelopment Services



TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Executive Summary	iii
1.0 INTRODUCTION	1
2.0 LIMITATIONS AND EXCEPTIONS	2
3.0 PROPERTY DESCRIPTION	3
4.0 ASBESTOS-CONTAINING MATERIALS INSPECTION	4
4.1 Previous Asbestos-Containing Materials Inspections	4
4.2 Asbestos Inspection Methodology	4
4.3 Sample Collection	4
4.4 Laboratory Analytical Results	5
5.0 CONCLUSIONS AND RECOMMENDATIONS	6
<u>Appendices</u>	
A Site Location Map	
B Resume and Accreditation of Kevin Ushery	
C Results of Sample Analysis and Chain-of-Custody Document	
D Asbestos Sample Table	

Executive Summary

ASTI Environmental (ASTI) was retained by Ann Arbor Housing Commission to conduct a limited asbestos-containing materials inspection of apartment units at 1506-1508 Broadway Street, Ann Arbor, Washtenaw County, Michigan (Property). The information and opinions rendered in this report are for reliance by Ann Arbor Housing Commission. ASTI will not distribute or publish this report without the consent of Ann Arbor Housing Commission, except as required by law or court order. The services provided by ASTI in completing this assessment have been provided in a manner consistent with the normal standards of the profession. No other warranties, expressed or implied, are made.

ASTI's scope of work included sampling of suspect homogeneous ACMs in general conformance with the National Emission Standards for Hazardous Air Pollutants (NESHAP) 40 CFR Part 61 Subpart M and ASTM E2356-10 Standard Practice for Comprehensive Building Asbestos Surveys. No destructive or intrusive sampling was conducted.

Based on the ACM inspection conducted by ASTI on October 15th and 16th, 2013, no ACMs were identified on the Property.

1.0 INTRODUCTION

ASTI Environmental (ASTI) was retained by Ann Arbor Housing Commission to conduct an asbestos-containing materials inspection of the apartment units at 1506-1508 Broadway Street, Ann Arbor, Michigan (Property). The inspection was performed for the benefit of Ann Arbor Housing Commission and ASTI acknowledges that only said party may rely on the contents and conclusions presented in this report.

2.0 LIMITATIONS AND EXCEPTIONS

ASTI's scope of services did not include destructive or intrusive testing of interstitial spaces, such as wall cavities, between buildings floors/sealed ceiling spaces, confined spaces, and fire doors. ASTI's scope of work included inspection of all units at the Property. Any suspect materials not sampled should be presumed to be asbestos-containing materials (ACMs). Suspect materials not identified within this report may be encountered in inaccessible cavities, chases, floor cavities, etc. during renovation activities. These materials must be presumed ACM until they can be sampled and analyzed for asbestos content.

3.0 PROPERTY DESCRIPTION

The Property is a residential apartment complex comprised of three buildings with a total of twenty apartment units. The buildings were constructed of wood frame with brick exterior and asphalt roofing. City of Ann Arbor online assessing records were reviewed for the property, however no building descriptions or date of construction were listed. A site location map is provided as Appendix A.

4.0 ASBESTOS-CONTAINING MATERIALS INSPECTION

Kevin Ushery of ASTI's Site Redevelopment Services (Asbestos Inspector No: A34315) conducted the inspection of the subject buildings for suspect ACMs on October 15th and 16th, 2013. Access was provided by Ann Arbor Housing Commission maintenance staff. Mr. Ushery inspected all accessible areas of the buildings. A copy of Mr. Ushery's resume and asbestos inspection certification are provided as Appendix B.

4.1 Previous Asbestos-Containing Materials Inspections

ASTI is unaware of any previous ACM inspections.

4.2 Asbestos Inspection Methodology

The ACM inspection was done in accordance with the National Emissions Standards for Hazardous Air Pollutants (NESHAP) requirements and ASTM E2356-10 Standard Practice for Comprehensive Building Asbestos Surveys. NESHAP defines ACM as a material containing greater than one percent asbestos. The survey included a visual inspection of the building, identifying homogeneous areas of suspect surfacing materials, thermal system insulation (TSI), and miscellaneous materials, and the sampling of suspect friable and non-friable materials. ASTI's scope of services did not include destructive or intrusive testing of interstitial spaces, such as wall cavities, between buildings floors/sealed ceiling spaces, and confined spaces.

4.3 Sample Collection

Samples were collected by physically removing a small piece of suspect material and placing it in a marked plastic bag corresponding to field notes. Samples were collected using wet methods as appropriate and the sample collection tool was cleaned prior to each use to avoid cross contamination of samples. The materials that were sampled by ASTI are as follows.

- Drywall and joint compound
- Plaster & mortar
- Floor tile and associated mastics
- Stuccos
- Base cove and associated adhesive

The suspect ACMs appeared to be in generally good condition during ASTI's inspection. ASTI collected 76 bulk samples from the types of suspect ACMs that are listed above.

The bulk samples were transmitted under chain-of-custody protocol to APEX Research, Inc. in Whitmore Lake, Michigan for asbestos analysis using polarized light microscopy with dispersion staining (PLM/DS) in accordance with the US Environmental Protection Agency's (US EPA's) "Interim Method for the Determination of Asbestos in Material Insulation Samples" (EPA-600/M4-82-020, December 1982). Positive samples containing less than 10 percent asbestos were additionally analyzed using the point count method for accurate percentage of asbestos contained in the sampled material.

4.4 Laboratory Analytical Results


The analytical results did not identify any ACMs.

A copy of the Certificate of Laboratory Analysis is included as Appendix C. A comprehensive list of sampled materials with analytical results is provided as Appendix D.

5.0 CONCLUSIONS AND RECOMMENDATIONS

Based on the results of the ACM inspection completed on the Property no materials were identified as ACM.

Attachment A
Site Location Map



Copyright © 2013 National Geographic Society, i-cubed

1504 - 1508 Broadway

Ann Arbor, MI



Created for: Ann Arbor Housing Commission
 Created by: LJD, November 26, 2013, ASTI Project 8563

Site Location Map

Attachment B

Resume and Accreditation of Kevin Ushery

RESUME

ASTI ENVIRONMENTAL



KEVIN USHERY
Environmental Scientist

PROFILE

Certifications/Training

OSHA Confined Space Entry Training – November 13, 2006
State of Michigan Licensed Lead-based Paint Inspector and Risk Assessor, P-03409, March, 2010
State of Michigan Asbestos Inspector Certification #A34315 – 2010
State of Michigan Asbestos Management Planner Certification #A34315 – 2009
State of Michigan Asbestos Contractor/Supervisor #A34315 – 2010
State of Ohio Asbestos Hazard Evaluation Specialist Certification #ES35016 – September 2010
State of Ohio Asbestos Hazard Abatement Air Monitoring Technician #AM 70566 – December 2010
American Petroleum Institute Service Station Contractor Safety Certification #54836643 – February 2009

Education

University of Phoenix, BS Business Management, 2005

Experience History

Abatement Marketing, EME Inc, Livonia, MI 2002 – 2004
Technician/Associate, EKS services, Detroit, MI, 2004 – 2005
Environmental Scientist, Traverse Group, Detroit, MI, 2005 – 2006
Environmental Scientist, TTL Associates, Inc., Plymouth, MI, 2006 – 2009
Technician/Associate, ASTI Environmental, Brighton, MI, 2009 – present

Professional Background

Mr. Ushery has provided environmental services for industrial, commercial, and private clients since 2002. His focus has been Lead Hazard Assessments, including Lead-based Paint Inspections and Risk Assessments per HUD and EPA requirements. He has also developed extensive experience in asbestos inspections and asbestos management. Specific tasks for this type of work include developing and implementing site sampling plans, sampling environmental media, site inspections, and preparing reports.

Years Experience: 6 years – Other Firms
 3 years – ASTI ENVIRONMENTAL

PROJECT EXPERIENCE

Asbestos Inspections

Conducted numerous asbestos inspections for residential commercial and industrial properties to determine whether ACMs were present and required remediation. Asbestos inspections have been performed in Michigan, Ohio, Tennessee, Indiana, Missouri and Kentucky.

Confined Space Entry, Asbestos Inspection

Conducted air monitoring testing for entry into tunnels below Blowing Green University in order to establish safe conditions for inspections for the presence of ACM.

Mold Sampling and Remediation

Indoor air quality sampling and remediation of Mold, in residential and commercial industries. Air sampling has been performed in Michigan.

Indoor Air Quality Sampling

Indoor air quality sampling for Asbestos, Lead and Mold, in residential and commercial buildings. Air quality sampling projects were performed in Michigan, Ohio, Indiana and Kentucky.

Lead-based Paint Clearance Reports, Redford

Conducted clearance testing in accordance with State of Michigan *Lead Control Rules* for township. Clearance sampling established that abatement contractor's work met EPA standards.

Lead-based Paint Inspection, Apartment Leasing Office, East Lansing

Conducted surface-by-surface testing for lead-based paint using a Niton XLp 300A x-ray fluorescence instrument in accordance with HUD and EPA protocols. Determined that no lead-based paint was present.

Lead-based Paint Inspection, Apartments, Detroit

Developed subsampling plan in accordance with HUD guidelines for 432 apartments. Conducted surface-by-surface testing for lead-based paint using a Niton XLp 300A x-ray fluorescence instrument in

accordance with HUD and EPA protocols. Provided report with results for more than 2,000 paint tests.

Lead-based Paint Clearance Reports, Ionia

Conducted clearance testing in accordance with State of Michigan *Lead Control Rules* for Ionia Housing Commission. Clearance sampling established that abatement contractor's work met EPA standards.

Lead-based Paint Inspections

and Risk Assessments, Residences in Lincoln Park
Project manager for a program of rapid assessment of 36 homes for NSP program. Conducted surface-by-surface testing for lead-based paint using a Niton XLp 300A x-ray fluorescence instrument in accordance with HUD and EPA protocols. Conducted dust wipe and soil sampling and documented paint condition and building condition as part of risk determination. Conducted asbestos inspection and sampling for same homes.

Lead-based Paint Inspections

and Risk Assessments, Two Residences in Detroit
Conducted surface-by-surface testing for lead-based paint using a Niton XLp 300A x-ray fluorescence instrument in accordance with HUD and EPA protocols. Conducted dust wipe and soil sampling and documented paint condition and building condition as part of risk determination. Provided report with results for two residences.

Lead-based Paint Inspections, Residences in Redford

Project manager for a program of rapid assessment of 4 homes for NSP program. Conducted surface-by-surface testing for lead-based paint using a Niton XLp 300A x-ray fluorescence instrument in accordance with HUD and EPA protocols. Conducted dust wipe and soil sampling and documented paint condition and building condition as part of risk determination. Provided report with results for more than 1,200 paint tests.

State of Michigan
 Department of Licensing and Regulatory Affairs
 Michigan Occupational Safety & Health Administration - Asbestos Program





Asbestos Inspector


Kevin E. Gardner-Ushery
 6240 Faust
 Detroit, MI 48228

Accreditation Number **A34315** Expiration Date **03/20/2014** DOB: 02/04/1974

This individual has satisfactorily met or exceeded the requirements of Michigan Public Act 440 of 1988, as amended, to be accredited as an Asbestos Inspector.

Accreditation card is not valid if altered. **104388**

State of Michigan
 Department of Licensing and Regulatory Affairs
 Michigan Occupational Safety & Health Administration - Asbestos Program


Asbestos Contractor/Supervisor

Kevin E. Gardner-Ushery
 6240 Faust
 Detroit, MI 48228

Accreditation Number **A34315** Expiration Date **03/20/2014** DOB: 02/04/1974

This individual has satisfactorily met or exceeded the requirements of Section 206 of the Toxic Substances Control Act to be accredited in the above discipline.

Accreditation card is not valid if altered. **104389**

Attachment C

Results of Sample Analysis and Chain-of-Custody Document



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 01 Cust. #: HA-01-A Material: Vinyl Floor 12x12 Location: Kitchen 1504-Apt 2 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%
Lab ID #: 48368 - 02 Cust. #: HA-01-B Material: Vinyl Floor 12x12 Location: Kitchen 1504-Apt-4 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%
Lab ID #: 48368 - 03 Cust. #: HA-01-C Material: Vinyl Floor 12x12 Location: Kitchen 1506-Apt-2 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 04 Cust. #: HA-01-D Material: Vinyl Floor 12x12 Location: Kitchen 1506-Apt-5 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%
Lab ID #: 48368 - 05 Cust. #: HA-01-E Material: Vinyl Floor 12x12 Location: Kitchen 1508-Apt-7 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%
Lab ID #: 48368 - 06 Cust. #: HA-01-F Material: Vinyl Floor 12x12 Location: Kitchen 1508-Apt-5 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 07 Cust. #: HA-01-G Material: Vinyl Floor 12x12 Location: Kitchen 1508-Apt-2 Appearance: white, fibrous, nonhomogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 10% Fiberglass - 10% Other - 80%
Lab ID #: 48368 - 08 Cust. #: HA-02-A Material: Drywall/Plaster Location: 1504-Apt-2 - Throughout Appearance: white, nonfibrous, homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 08a Cust. #: HA-02-A Material: Mortar Location: 1504-Apt-2 - Throughout Appearance: grey, fibrous, homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Hair - 2% Other - 98%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 09 Cust. #: HA-02-B Material: Drywall/Plaster Location: 1504-Apt-4 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 09a Cust. #: HA-02-B Material: Mortar Location: 1504-Apt-4 - Throughout Appearance: grey,fibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Hair - 2% Other - 98%
Lab ID #: 48368 - 10 Cust. #: HA-02-C Material: Drywall/Plaster Location: 1506-Apt-2 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 10a Cust. #: HA-02-C Material: Mortar Location: 1506-Apt-2 - Throughout Appearance: grey,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 11 Cust. #: HA-02-D Material: Drywall/Plaster Location: 1506-Apt-5 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 11a Cust. #: HA-02-D Material: Mortar Location: 1506-Apt-5 - Throughout Appearance: grey,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 12 Cust. #: HA-02-E Material: Drywall/Plaster Location: 1508-Apt-7 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 12a Cust. #: HA-02-E Material: Plaster Location: 1508-Apt-7 - Throughout Appearance: white,nonfibrous,homogenous Layer: 2 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 12b Cust. #: HA-02-E Material: Mortar Location: 1508-Apt-7 - Throughout Appearance: grey,fibrous,homogenous Layer: 3 of 3	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 13 Cust. #: HA-02-F Material: Plaster Location: 1508-Apt-5 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 13a Cust. #: HA-02-F Material: Mortar Location: 1508-Apt-5 - Throughout Appearance: grey,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%
Lab ID #: 48368 - 14 Cust. #: HA-02-G Material: Plaster Location: 1508-Apt-2 - Throughout Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 14a Cust. #: HA-02-G Material: Mortar Location: 1508-Apt-2 - Throughout Appearance: grey,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%
Lab ID #: 48368 - 15 Cust. #: HA-03-A Material: Floor Tile 12x12 - Brown Location: Closet 1504-Apt-2 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 100%
Lab ID #: 48368 - 15a Cust. #: HA-03-A Material: Mastic Location: Closet 1504-Apt-2 Appearance: black,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 16 Cust. #: HA-03-B Material: Floor Tile 12x12 - Brown Location: Closet 1504-Apt-4 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 16a Cust. #: HA-03-B Material: Mastic Location: Closet 1504-Apt-4 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 17 Cust. #: HA-03-C Material: Floor Tile 12x12 - Brown Location: Closet 1506-Apt-2 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 17a Cust. #: HA-03-C Material: Mastic Location: Closet 1506-Apt-2 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 18 Cust. #: HA-03-D Material: Floor Tile 12x12 - Brown Location: Closet 1506-Apt-5 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 18a Cust. #: HA-03-D Material: Mastic Location: Closet 1506-Apt-5 Appearance: black,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 19 Cust. #: HA-03-E Material: 12x12 Floor Tile - Brown Location: Closet 1508-Apt-7 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 19a Cust. #: HA-03-E Material: Mastic Location: Closet 1508-Apt-7 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 20 Cust. #: HA-03-F Material: 12x12 Floor Tile - Brown Location: Closet 1508-Apt-6 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 20a Cust. #: HA-03-F Material: Mastic Location: Closet 1508-Apt-6 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 21 Cust. #: HA-03-G Material: 12x12 Floor Tile - Brown Location: Closet 1500-Apt-2 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 21a Cust. #: HA-03-G Material: Mastic Location: Closet 1500-Apt-2 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 22 Cust. #: HA-04-A Material: Brown Covebase Location: Kitchen 1504-Apt-4 Appearance: brown,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 23 Cust. #: HA-04-B Material: Brown Covebase Location: Kitchen 1506-Apt-2 Appearance: brown,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 24 Cust. #: HA-04-C Material: Brown Covebase Location: Kitchen 1508-Apt-7 Appearance: brown,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 25 Cust. #: HA-04-D Material: Brown Covebase Location: Kitchen 1508-Apt-5 Appearance: brown,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 26 Cust. #: HA-04-E Material: Brown Covebase Location: Kitchen 1508-Apt-2 Appearance: brown,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 26a Cust. #: HA-04-E Material: Glue Location: Kitchen 1508-Apt-2 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 27 Cust. #: HA-05-A Material: Stucco Location: Kitchen 1504-Apt-1 Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 28 Cust. #: HA-05-B Material: Stucco Location: Living 1504-Apt-1 Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 29 Cust. #: HA-05-C Material: Stucco Location: Hall 1504-Apt-1 Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 30 Cust. #: HA-06-A Material: 2x2 Vinyl Floor Location: Kitchen 1506-Apt-4 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%
Lab ID #: 48368 - 31 Cust. #: HA-06-B Material: 2x2 Vinyl Floor Location: Kitchen 1506-Apt-4 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%
Lab ID #: 48368 - 32 Cust. #: HA-06-C Material: 2x2 Vinyl Floor Location: Kitchen 1506-Apt-4 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:
Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 33 Cust. #: HA-07-A Material: Stucco - Wall Location: Basement 1506-5-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%
Lab ID #: 48368 - 34 Cust. #: HA-07-B Material: Stucco - Wall Location: Basement 1506-5-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%
Lab ID #: 48368 - 35 Cust. #: HA-07-C Material: Stucco - Wall Location: Basement 1506-5-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 1% Other - 99%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:
Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 36 Cust. #: HA-08-A Material: Stucco Ceiling Location: Living Rm-1508-Apt-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 4% Other - 96%
Lab ID #: 48368 - 37 Cust. #: HA-08-B Material: Stucco Ceiling Location: Living Rm-1508-Apt-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 5% Other - 95%
Lab ID #: 48368 - 38 Cust. #: HA-08-C Material: Stucco Ceiling Location: Living Rm-1508-Apt-8 Appearance: white, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Cellulose - 5% Other - 95%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 39 Cust. #: HA-09-A Material: 2x2 Vinyl Floor Location: 1508-Apt-1 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%
Lab ID #: 48368 - 40 Cust. #: HA-09-B Material: 2x2 Vinyl Floor Location: 1508-Apt-1 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%
Lab ID #: 48368 - 41 Cust. #: HA-09-C Material: 2x2 Vinyl Floor Location: 1508-Apt-1 Appearance: beige, fibrous, homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Fiberglass - 5% Other - 95%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 42 Cust. #: HA-10-A Material: Cream Covebase Location: 1506-Apt-4 Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 42a Cust. #: HA-10-A Material: Glue Location: 1506-Apt-4 Appearance: white,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 43 Cust. #: HA-10-B Material: Cream Covebase Location: 1508-Apt-1 Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 44 Cust. #: HA-10-C Material: Cream Covebase Location: 1508-Apt-1 Appearance: white,nonfibrous,homogenous Layer: 1 of 1	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 45 Cust. #: HA-11-A Material: 12x12 White Floor Tile Location: 1504-1506-1508 Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 45a Cust. #: HA-11-A Material: Mastic Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 46 Cust. #: HA-11-B Material: 12x12 White Floor Tile Location: 1504-1506-1508 Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 46a Cust. #: HA-11-B Material: Mastic Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 47 Cust. #: HA-11-C Material: 12x12 White Floor Tile Location: 1504-1506-1508 Appearance: white,nonfibrous,homogenous Layer: 1 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 47a Cust. #: HA-11-C Material: Mastic Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 2 of 2	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 48 Cust. #: HA-12-A Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 1 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 48a Cust. #: HA-12-A Material: 12x12 Pink Floor Tile Location: 1504-1506-1508 Appearance: pink,nonfibrous,homogenous Layer: 2 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 48b Cust. #: HA-12-A Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 3 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 49 Cust. #: HA-12-B Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 1 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 49a Cust. #: HA-12-B Material: 12x12 Pink Floor Tile Location: 1504-1506-1508 Appearance: pink,nonfibrous,homogenous Layer: 2 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:

Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 49b Cust. #: HA-12B Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 3 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 50 Cust. #: HA-12-C Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 1 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: 48368 - 50a Cust. #: HA-12-C Material: 12x12 Pink Floor Tile Location: 1504-1506-1508 Appearance: pink,nonfibrous,homogenous Layer: 2 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0



Certificate of Laboratory Analysis

Test Method, Polarized Light Microscopy (PLM)

Project: Ann Arbor Housing
Project # 8563

Report To:
Mr. Kevin Ushery
ASTI Environmental
10448 Citation Dr.
Brighton, MI 48116

ARI Report # 13-48368
Date Collected: 10/23/13
Date Received: 10/24/13
Date Analyzed: 10/25/13
Date Reported: 10/29/13

Sample Information	Asbestos Type/Percent	Non-Asbestos
Lab ID #: 48368 - 51b Cust. #: HA-12-C Material: Glue Location: 1504-1506-1508 Appearance: yellow,nonfibrous,homogenous Layer: 3 of 3	Asbestos Present: NO No Asbestos Observed	Other - 100%
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	
Lab ID #: Cust. #: Material: Location: Appearance: Layer: of	Asbestos Present:	

For Layered Samples, each component will be analyzed and reported separately.

Robert T. Letarte Jr., Laboratory Director

Test Method EPA 600/R-93/116 was used to analyze the above samples. Matrix interference and/or resolution limits may yield false/negative results in certain circumstances. Suspect floor tiles containing <1% should be tested with SEM or TEM. This certificate of analysis relates only to the samples tested and to insure the integrity of the results, may only be reproduced in full. This certificate may not be used by the customer to claim product endorsement by NVLAP or any agency of the US Government. APEX Research Inc. is not responsible for the accuracy of the results for layered samples or samples comprising multiple materials. Liability limited to cost of analysis.



NVLAP Lab Code 102118-0

APEX # **48368**

APEX Research, Inc.

054 Hi Tech Drive, Whitmore Lake, MI 48189. Phone: (734) 449 - 9990, Fax (734) 449 - 9991.
 Web Site: <http://apexresearch-inc.com>. Email: Bob.Letarte@apexresearchlab.com



Customer Name: ASTI Environmental
 Address: P.O. Box 2160
 City, St., Zip: Brighton, MI 48116
 Phone: _____ Fax: _____

Date of Survey: 10-23-13
 Project: ANN ARBOR HOUSING
 Project # 8563
 Contact Person: K. USTERY
 Email: NSP@ASTI-ENV.COM

Lab Use Only
 Log-In: _____
 Report: _____
 Fax: _____
 Verbal: _____
 Email: _____

Turn Around Times: (Circle One)

Rush 24 hour
 48 hour 72 hour
 Other: _____ TTP yes / no
 (Test Till Positive)

***Terms and conditions on the other side.
Asbestos: Bulk Wipe _____ Point Count PCM _____
Lead: Bulk _____ Wipe _____ Air _____ Paint _____ Soil _____
Mold: Bulk _____ Tape _____ BioSIS _____ Other _____ Viable _____
TEM: Bulk/NOP _____ AHERA _____ EPA Level II _____ Other _____

Lab ID	Customer ID #	Material/Location	Volume	Area	Results
1	HA-01-A	Vinyl Floor 12x12 Cream -1504-APT 2	KITCHEN	30	
2	B		1504-APT 4		
3	C		1506-APT 2		
4	D		1506-APT 5		
5	E		1508-APT 7		
6	F		1508-APT 5		
7	G		1508-APT 2		
8	HA-02-A	DRY WALL / PLASTER WALL / 504-APT 2	Throughout	N/A	
9	B		1504-APT 4		
10			1506-APT 2		
11			1506-APT 5		

Relinquished By: Kevin Ustery
 Date: 10-23-13
 Revision Date: June/2011

Received By: [Signature]
 Date: 10-23-13
 APEX RESEARCH

Relinquished By: _____
 Date: _____
 Relinquished By: _____
 Date: _____

APEX Research, Inc.

11054 Hi Tech Drive, Whitmore Lake, MI 48189. Phone: (734) 449 - 9990, Fax (734) 449 - 9991.

Web Site: <http://apexresearch-inc.com>. Email: Bob.Letarte@apexresearchlab.com



Customer Name: ASTI Environmental
 Address: P.O. Box 2160
 City, St., Zip: Brighton, MI 48116
 Phone: _____ Fax: _____

Date of Survey: _____
 Project: _____
 Project # _____
 Contact Person: K. Ushery
 Email: NSP@asti-env.com

Lab Use Only
 Log-In: _____
 Report: _____
 Fax: _____
 Verbal: _____
 Email: _____

Turn Around Times: (Circle One)

Rush 24 hour
 48 hour 72 hour
 Other: _____ TTP yes / no
 (Test Till Positive)

***Terms and conditions on the other side.
Asbestos: Bulk Wipe _____ Point Count PCM _____
Lead: Bulk _____ Wipe _____ Air _____ Paint _____ Soil _____
Mold: Bulk _____ Tape _____ BioSIS _____ Other _____ Viable _____
TEM: Bulk/NOP _____ AHERA _____ EPA Level II _____ Other _____

48362

Lab ID	Customer ID #	Material/Location	Volume	Area	Results
12	HA-02-E	Drywall/PLASTER WALL-150B-APT-7	THROUGHOUT	N/A	
13	F	150B-APT-5			
14	G	150B-APT-2			
15	HA-03-A	12x12 BROWN FLOOR TILE-1504-APT-2	Closet	BSF	
16	B	1504-APT-2			
17	C	1506-APT-2			
18	D	1506-APT-5			
19	E	1508-APT-7			
20	F	1508-APT-6			
21	G	1500-APT-2			

RECEIVED

APR 24 2013
 APEX RESEARCH

Relinquished By: Kevin Ushery
 Date: 10-23-13

Received By: [Signature]
 Date: 10/24/13

Relinquished By: _____
 Date: _____

Relinquished By: _____
 Date: _____

APEX Research, Inc.

11054 Hi Tech Drive, Whitmore Lake, MI 48189. Phone: (734) 449 - 9990, Fax (734) 449 - 9991.

Web Site: <http://apexresearch-inc.com>. Email: Bob.Letarte@apexresearchlab.com



Customer Name: ASTI Environmental
 Address: P.O. Box 2160
 City, St., Zip: Brighton, MI 48116
 Phone: _____ Fax: _____

Date of Survey: _____
 Project: _____
 Project # _____
 Contact Person: K. Ushtery
 Email: NSP@asti-env.com

Lab Use Only
 Log-In: _____
 Report: _____
 Fax: _____
 Verbal: _____
 Email: _____

Turn Around Times: (Circle One)

Rush 24 hour
 48 hour 72 hour
 Other: _____ TTP yes / no
 (Test Till Positive)

***Terms and conditions on the other side.
Asbestos: Bulk Wipe _____ Point Count PCM _____
Lead: Bulk _____ Wipe _____ Air _____ Paint _____ Soil _____
Mold: Bulk _____ Tape _____ BioSIS _____ Other _____ Viable _____
TEM: Bulk/NOP _____ AHERA _____ EPA Level II _____ Other _____

42362

Lab ID	Customer ID #	Material/Location	Volume	Area	Results
22	HA-04 - A	BROWN COVER BASE - 1504 - APT- 4	KITCHEN	3OLF	
23	B	1506 - APT- 2			
24	C	1508 - APT- 7			
25	D	1508 - APT- 5			
26	E	1508 - APT- 2			
27	HA-05 - A	STucco - 1504 - APT 1	KITCHEN		
28	B		LIVING		
29	C		HALL		
30	HA-06 - A	2x2 mixed TAN VINYL FLOORING - 1506 - APT 4	KITCHEN		
31	B				
32	C				

Relinquished By: Kevin Ushtery
 Date: 10-23-13

Received By: [Signature]
 Date: 10/23/13

Relinquished By: _____
 Date: _____

Relinquished By: _____
 Date: _____

APEX Research, Inc.

11054 Hi Tech Drive, Whitmore Lake, MI 48189. Phone: (734) 449 - 9990, Fax (734) 449 - 9991.
 Web Site: <http://apexresearch-inc.com>. Email: Bob.Letarte@apexresearchlab.com



Customer Name: ASTI Environmental
 Address: P.O. Box 2160
 City, St., Zip: Brighton, MI 48116
 Phone: _____ Fax: _____

Date of Survey: _____
 Project: _____
 Project # _____
 Contact Person: K. Ushery
 Email: NSP@ASTI-ENV.COM

Lab Use Only
 Log-In: _____
 Report: _____
 Fax: _____
 Verbal: _____
 Email: _____

Turn Around Times: (Circle One)

Rush _____
 48 hour _____
 Other: _____
 24 hour
 72 hour _____
 TTP yes / no _____
 (Test Till Positive)

***Terms and conditions on the other side.
Asbestos: Bulk Wipe _____ Point Count PCM _____
Lead: Bulk _____ Wipe _____ Air _____ Paint _____ Soil _____
Mold: Bulk _____ Tape _____ BioSIS _____ Other _____ Viable _____
TEM: Bulk/NOP _____ AHERA _____ EPA Level II _____ Other _____

48362

Lab ID	Customer ID #	Material/Location	Volume	Area	Results
33	HA-07 - A	Stucco WALL - 1506 / 5-B BASEMENT			
34	B				
35	C				
36	HA-08 - A	Stucco ceiling - 1508 - APT 3 Living Rm			
37	B				
38	C				
39	HA-09 - A	Vinyl Floor 2 x 2 mixed beige - 1508 - APT 1		305F	
40	B				
41	C				

RECEIVED

Relinquished By: Kevin Ushery
 Date: 10-23-13

Received By: [Signature]
 Date: 10/24/13

Relinquished By: _____
 Date: _____

Relinquished By: _____
 Date: _____

APEX Research, Inc.

11054 Hi Tech Drive, Whitmore Lake, MI 48189. Phone: (734) 449 - 9990, Fax (734) 449 - 9991.

Web Site: <http://apexresearch-inc.com>. Email: Bob.Letarte@apexresearchlab.com



Customer Name: ASTI Environmental
 Address: P.O. Box 2160
 City, St., Zip: Brighton, MI 48116
 Phone: _____ Fax: _____

Date of Survey: _____
 Project: _____
 Project # _____
 Contact Person: K. Ustery
 Email: NSP@asti-env.com

Lab Use Only
 Log-In: _____
 Report: _____
 Fax: _____
 Verbal: _____
 Email: _____

Turn Around Times: (Circle One)

Rush 24 hour
 48 hour 72 hour
 Other: _____ TTP yes / no
 (Test Till Positive)

***Terms and conditions on the other side.
Asbestos: Bulk Wipe _____ Point Count PCM _____
Lead: Bulk _____ Wipe _____ Air _____ Paint _____ Soil _____
Mold: Bulk _____ Tape _____ BioSIS _____ Other _____ Viable _____
TEM: Bulk/NOP _____ AHERA _____ EPA Level II _____ Other _____

48369

Lab ID	Customer ID #	Material/Location	Volume	Area	Results
42	HA-10-A	Cream Cove Base - 1506-APT 4		30LF	
43	B	1508 APT 1			
44	C	1508 APT 1			
45	HA-11-A	12x12 White Floor Tile - 1504-1506-1508		200LF	
46	B				
47	C				
48	HA-12-A	12x12 Pink Floor Tile - 1504-1506-1508			
49	B				
50	C				

RECEIVED

Relinquished By: Kevin Mahoney
 Date: 10-23-13
 Revision Date: June/2011

Received By: [Signature]
 Date: 10/24/13

Relinquished By: _____
 Date: _____

Relinquished By: _____
 Date: _____

APEX RESEARCH

Attachment D
Asbestos Sample Table

**Attachment D- Asbestos Sample Results
1504-1508 Broadway
Ann Arbor, Michigan
ASTI Project No. 8563**

ASTI Sample No.	Material/Description	Functional Space	Sample Location	Friability	Asbestos Result	Quantity
1A	Vinyl Flooring/ 12"x12" cream	1504-APT 2	Kitchen floor	NF	NAD	~30 SF per Unit
1B	Vinyl Flooring/ 12"x12" cream	1504-APT 4	Kitchen floor	NF	NAD	
1C	Vinyl Flooring/ 12"x12" cream	1506-APT 2	Kitchen floor	NF	NAD	
1D	Vinyl Flooring/ 12"x12" cream	1506-APT 5	Kitchen floor	NF	NAD	
1E	Vinyl Flooring/ 12"x12" cream	1504-APT 7	Kitchen floor	NF	NAD	
1F	Vinyl Flooring/ 12"x12" cream	1508-APT 5	Kitchen floor	NF	NAD	
1G	Vinyl Flooring/ 12"x12" cream	1508-APT 2	Kitchen floor	NF	NAD	
2A	Drywall/Plaster	1504-APT 2	Wall	NF	NAD	NQ
	Mortar					
2B	Drywall/Plaster	1504-APT 4	Wall	NF	NAD	
	Mortar					
2C	Drywall/Plaster	1506-APT 2	Wall	NF	NAD	
	Mortar					
2D	Drywall/Plaster	1506-APT 5	Wall	NF	NAD	
	Mortar					
2E	Drywall/Plaster	1508-APT 7	Wall	NF	NAD	
	Mortar					
2F	Drywall/Plaster	1508-APT 5	Wall	NF	NAD	
	Mortar					
2G	Drywall/Plaster	1508-APT 2	Wall	NF	NAD	
	Mortar					
3A	Floor tile 12"x12" Brown	1504-APT 2	Closet floor	NF	NAD	~8 SF per Unit
	Mastic					
3B	Floor tile 12"x12" Brown	1504-APT 4	Closet floor	NF	NAD	
	Mastic					
3C	Floor tile 12"x12" Brown	1506-APT 2	Closet floor	NF	NAD	
	Mastic					
3D	Floor tile 12"x12" Brown	1506-APT 5	Closet floor	NF	NAD	
	Mastic					
3E	Floor tile 12"x12" Brown	1508-APT 7	Closet floor	NF	NAD	
	Mastic					
3F	Floor tile 12"x12" Brown	1508-APT 6	Closet floor	NF	NAD	
	Mastic					
3G	Floor tile 12"x12" Brown	1508-APT 2	Closet floor	NF	NAD	
	Mastic					
4A	Brown Covebase	1504-APT 4	Kitchen walls	NF	NAD	~30 LF per Unit
4B	Brown Covebase	1506-APT 2	Kitchen walls	NF	NAD	
4C	Brown Covebase	1508-APT 7	Kitchen walls	NF	NAD	
4D	Brown Covebase	1508-APT 5	Kitchen walls	NF	NAD	
4E	Brown Covebase/Glue	1508-APT 2	Kitchen walls	NF	NAD	

F = Friable
NF = Non Friable
NAD = No Asbestos Detected

lf = Lineal Feet
ft2 = Square Feet

Bold = Positive for asbestos
NQ = Not Quantified
NA = Not Analyzed

**Attachment D- Asbestos Sample Results
1504-1508 Broadway
Ann Arbor, Michigan
ASTI Project No. 8563**

ASTI Sample No.	Material/Description	Functional Space	Sample Location	Friability	Asbestos Result	Quantity
5A	Stucco	1504-APT 1	Kitchen ceiling	F	NAD	NQ
5B	Stucco	1504-APT 1	Living room ceiling	F	NAD	
5C	Stucco	1504-APT 1	Hall ceiling	F	NAD	
6A	Vinyl Flooring/ 2'x2' tan	1506-APT 4	Kitchen floor	NF	NAD	~600 SF per Unit
6B	Vinyl Flooring/ 2'x2' tan	1506-APT 4	Kitchen floor	NF	NAD	
6C	Vinyl Flooring/ 2'x2' tan	1506-APT 4	Kitchen floor	NF	NAD	
7A	Stucco	1506-5-8	Basement wall	F	NAD	NQ
7B	Stucco	1506-5-8	Basement wall	F	NAD	
7C	Stucco	1506-5-8	Basement wall	F	NAD	
8A	Stucco	1508-APT 8	Living room ceiling	F	NAD	NQ
8B	Stucco	1508-APT 8	Living room ceiling	F	NAD	
8C	Stucco	1508-APT 8	Living room ceiling	F	NAD	
9A	Vinyl Flooring/ 12"x12" mixed beige	1508-APT 1	Bathroom floor	NF	NAD	~30 SF per Unit
9B	Vinyl Flooring/ 12"x12" mixed beige	1508-APT 1	Bathroom floor	NF	NAD	
9C	Vinyl Flooring/ 12"x12" mixed beige	1508-APT 1	Bathroom floor	NF	NAD	
10A	Cream Covebase/Glue	1506-APT 4	Kitchen wall base	NF	NAD	NQ
10B	Cream Covebase/Glue	1508-APT 1	Kitchen wall base	NF	NAD	
10C	Cream Covebase	1508-APT 1	Kitchen wall base	NF	NAD	
11A	Floor tile 12"x12" white	1504	Hall floor	NF	NAD	~200 SF per Unit
	Mastic					
11B	Floor tile 12"x12" white	1506	Hall floor	NF	NAD	
	Mastic					
11C	Floor tile 12"x12" white	1508	Hall floor	NF	NAD	
	Mastic					
12A	Glue	1504	Hall floor	NF	NAD	
	Floor tile 12"x12" pink					
	Glue					
12B	Glue	1506	Hall floor	NF	NAD	
	Floor tile 12"x12" pink					
	Glue					
12C	Glue	1508	Hall floor	NF	NAD	
	Floor tile 12"x12" pink					

F = Friable
NF = Non Friable
NAD = No Asbestos Detected

lf = Lineal Feet
ft2 = Square Feet

Bold = Positive for asbestos
NQ = Not Quantified
NA = Not Analyzed

ASTI ENVIRONMENTAL
8,000 ENVIRONMENTAL INVESTIGATION, REMEDIATION, COMPLIANCE AND
RESTORATION PROJECTS THROUGHOUT THE GREAT LAKES SINCE 1985.

OUR SERVICES INCLUDE:

- **ASBESTOS, LEAD, MOLD, AND RADON ASSESSMENTS**
- **BROWNFIELD/GREYFIELD REDEVELOPMENT STRATEGIES**
- **DEVELOPMENT INCENTIVES**
- **ECOLOGICAL ASSESSMENTS AND RESTORATION**
- **ENVIRONMENTAL ASSESSMENTS AND IMPACT STATEMENTS**
- **ENVIRONMENTAL OPPORTUNITIES ASSESSMENT**
- **GIS MAPPING**
- **HAZARD MITIGATION PLANNING**
- **MINING AND RECLAMATION ASSISTANCE**
- **OPERATION AND MAINTENANCE**
- **PHASE I ESA AND ENVIRONMENTAL DUE DILIGENCE**
- **REGULATORY COMPLIANCE AND PERMITTING**
- **SOIL AND GROUNDWATER ASSESSMENTS**
- **SOIL AND GROUNDWATER REMEDIATION**
- **STORAGE TANK COMPLIANCE AND CLOSURE**
- **THREATENED AND ENDANGERED SPECIES SURVEYS**
- **WATERSHED AND STORMWATER MANAGEMENT PROGRAMS**
- **WETLAND DELINEATION, PERMITTING, MITIGATION AND BANKING**