

## Lead Based Paint Contamination by Property – updated 07/2021

Building	Identified Lead Based Paint
Baker Commons	Built 1981
Broadway	LBP in hallways, 1504 porch roof and all interior doors, walls, windows – see test results
Creekside Court	New construction 2020
Garden	Cleared
Green Baxter	Cleared except 1725 lead dust on basement floor which was abated
Hikone	Cleared
Hillside Manor On Pennsylvania	Built in 1998
Lurie Terrace 600 W Huron	Only on Exterior Wooden underhang
Mallett's Creek on Main	Built in 1998
Maple Meadows on S Maple	Cleared
Miller Manor	Cleared except 408 lead dust on kitchen floor abated
Oakwood	Needs to be tested
S. Seventh	All units cleared except 251 S Seventh which had LBP on North and East wall of living room, west wall of bedroom and ceiling of furnace closet. 251 Abated.
Upper Platt 3451 – 3457 Platt	1996 test showed LBP on wood siding only, when re-surveyed in 2014 the siding had been removed already
West Arbor	New Construction 2016, 3-bdr duplexes built 1998
W. Washington	Cleared
State Crossing	New construction 2020
S. Industrial	Some cinder block walls, 3 doors, soffit (see study for specific rooms)